





www.groundsure.com


Supplied by: www.emapsite.com sales@emapsite.com


© Crown copyright and database rights 2019 Ordnance Survey 100035207 Production date: 10 June 2022

































Map legend available at: www.groundsure.com/sites/default/files/groundsure_legend.pdf





www.groundsure.com



Supplied by: www.emapsite.com sales@emapsite.com

© Crown copyright and database rights 2019 Ordnance Survey 100035207 Production date: 10 June 2022







www.groundsure.com



Supplied by: www.emapsite.com sales@emapsite.com


© Crown copyright and database rights 2019 Ordnance Survey 100035207 Production date: 10 June 2022






Copyright N/A Levelled N/A









Groundsure Insights www.groundsure.com




Supplied by: www.emapsite.com sales@emapsite.com


© Crown copyright and database rights 2019 Ordnance Survey 100035207 Production date: 10 June 2022





















APPENDIX III

PHOTOGRAPHIC REPORT

Ecologia

EES 22.108.2 – New Street Client: Classicus Estates Ltd.



Plate 1. Access to the north of the Site via a wide, single metal gate



Plate 3. Looking south from the northern extent of the Site, open grassland and mature trees present.



Plate 2. View looking north from the entrance to the Site from New Street (to the south of the Site). Vacant buildings present.



Plate 4. Western boundary of the Site, wire and wood fence separating the Site from the adjacent property.



Plate 5. Southern boundary of the Site, mature trees and hedgerows separate the Site from the road beyond.



Plate 6. Looking east from the center of Site, wood panel fencing and mature trees separate the Site from residential properties beyond.





Plate 7. White goods present within one of the buildings present in the south of the Site.



Plate 9. Ccontainer labelled as containing petrol, one unlabeled container, and other waste within one of the buildings present in the south of the Site.



Plate 8. A gas cylinder and other waste within one of the buildings present in the south of the Site.



Plate 10.. Stockpiled materials and other waste within one of the buildings present in the south of the Site.



Plate 11. Paint containers and other waste within one of the buildings present in the south of the Site.



Plate 12.. A Greenhouse present in the southwest corner of the Site

