


LILE DRAINAGE SYSTEM  
RUSHFIELD - BONNINGTON  
ROMNEY MARSH FARMS LTD

21/9/77  
No pipes  
found

No pipes  
when drilled  
scheme Oct 1978

19 heads  
found when  
ditch excavated  
20/9/77



DAK FARM  
50  
958

177  
20.142

182  
30.001

184  
28.130

185  
12.073

186  
223

174  
20.373

HURST FARM

Sheepfold

F.F.  
C.D.  
47  
283

C.R.